


PRODUCT UPDATE ANNOUNCEMENT

New Alert Inputs Now Available for Invita 564 Thermostat

Tekmar is excited to introduce five new alert inputs for the Invita 564 thermostat!

With this update, users will automatically receive text or email notifications when a fault is detected in their ERV, heat pump, boiler, or sump pump systems.

Tekmar has also added a “Service Needed” alert to notify users when a third-party device triggers a warning or when general system maintenance is required. For customers currently using the Water Leak input, no action is required—the default setting will remain Water Leak. An email will be sent to customers informing them of this update. This enhancement ensures that alerts are more specific to the system connected to the Invita, providing users with timely and actionable information.



Availability

The software will automatically update for connected users on December 8, 2025.

Literature

The Invita WiFi Thermostat 564 IOM and job record are updated on Tekmar's [Website](#).

If you have any questions, please do not hesitate to contact Hydronic Systems at customerservice@hydronicsystems.ca or phone 416-675-7651.